



Home About Us Contact Us View Cart My Account FAQ

username

LOGIN

New Account »
Forgot Password?

Aluminum oxide

GO

Advanced Search »

Ads by Google

Deep Discounts on Rockets

Estes, Aerotech, Quest and more
Very low prices on all major brands
www.a2zhobbies.com

US Army - Official Site

Earn \$2,000 when you refer someone to the Army.
Details inside!
www.army.mil

RocketFuelPump

lower cost, higher reliability rocket fuel pump system
www.rocketfuelpump.com

Minneapolis Toy Rockets

Find hobby supplies in your area. We have over 40,000 items.
hubobbycenter.net



Mechanical, Industrial and Civil Eng. ▾ Civil Engineering

Studies of the Exhaust Products from Solid Propellant Rocket Motors

Authors: [R. Dawbarn](#); [M. Kinslow](#); [ARNOLD ENGINEERING DEVELOPMENT CENTER ARNOLD AFS TN](#)

Abstract: This study was undertaken to determine the feasibility of conducting environmental chamber tests on the physical processes which occur when a solid rocket motor exhaust mixes with the ambient atmosphere. Of particular interest was the interaction between hydrogen chloride, **aluminum oxide**, and water vapor. The program consisted of three phases: (1) building a small rocket motor and using it to provide the exhaust species in a controlled environment; (2) evaluating instruments used to detect and measure HCl concentrations and if possible determining whether the HCl existed in the gaseous state or as an acid aerosol; (3) monitoring a series of 6.4-percent scale space shuttle motor tests and comparing the results to the environmental chamber studies. Eighteen firings were conducted in an environmental chamber with the initial ambient relative humidity set at values from 29 to 100 percent. Two additional firings were made in a large shed, and four were made on an open concrete apron. Six test firings at MSFC were monitored, and the ground level concentrations are reported. Evidence is presented which shows that the larger Al₂O₃ (5 to 50 micrometers) particles from the rocket motor can act as condensation nuclei. Under appropriate ambient conditions where there is sufficient water vapor this results in the formation of an acid aerosol. Droplets of this acid were detected both in the environmental chamber and in the scaled shuttle engine tests.

Adobe PDF - \$26.95

Printed Format - \$29.95

ADD TO CART

Please check the box for the format you wish to order.

[Shipping Terms](#)
[About Electronic Delivery](#)

[Email This Abstract](#)

Limitations: APPROVED FOR PUBLIC RELEASE
Description: Final rept. 1 Jul 1973-30 Jun 1975
Pages: 115
Report Date: SEP 1976
Report Number: A965920

Keywords relating to this report:

- ✦ [COMBUSTION PRODUCTS](#)
- ✦ [CONDENSATION NUCLEI](#)
- ✦ [CONTAMINATION](#)
- ✦ [ENVIRONMENTAL TESTS](#)
- ✦ [EXHAUST GASES](#)
- ✦ [HYDROCHLORIC ACID](#)
- ✦ [HYDROGEN CHLORIDE](#)
- ✦ [INSTRUMENTATION](#)
- ✦ [PARTICLES](#)
- ✦ [SOLID PROPELLANT ROCKET ENGINES](#)
- ✦ [SPACE SHUTTLES](#)
- ✦ [TEST FACILITIES](#)
- ✦ [WATER VAPOR](#)

[« Back to search](#)

[Home](#) | [About Us](#) | [Contact Us](#) | [View Cart](#) | [Customer Service](#) | [Shipping Terms](#) | [Advanced Search](#) | [Privacy Policy](#) | [Restrictions on PDF Usage](#)

© 2001-2008 Storming Media LLC. All rights reserved.